

How to convert inches to millimetres

(1 INCH = 25.4 MM EXACTLY)

Read from left to right – pick your fraction, decimal, or mm measurement.

Example = convert **1/64"** to **mm**. Find **1/64** and read to the right under **mm**!

You will see **0.3969** under the mm column.

Another example = convert **0.125 decimal** to **inches**. Look down the decimal column until you find **0.125**, then follow that line to the left to find **1/8** inches or look in the right column for mm!

fraction	decimal	mm	fraction	decimal	mm	fraction	decimal	mm
1/64	0.0156	0.3969	1 1/64	1.0156	25.7969	2 1/64	2.0156	51.1969
1/32	0.0313	0.7938	1 1/32	1.0313	26.1938	2 1/32	2.0313	51.5938
3/64	0.0469	1.1906	1 3/64	1.0469	26.5906	2 3/64	2.0469	51.9906
1/16	0.0625	1.5875	1 1/16	1.0625	26.9875	2 1/16	2.0625	52.3875
5/64	0.0781	1.9844	1 5/64	1.0781	27.3844	2 5/64	2.0781	52.7844
3/32	0.0938	2.3813	1 3/32	1.0938	27.7813	2 3/32	2.0938	53.1813
7/64	0.1094	2.7781	1 7/64	1.1094	28.1781	2 7/64	2.1094	53.5781
1/8	0.1250	3.1750	1 1/8	1.1250	28.5750	2 1/8	2.1250	53.9750
9/64	0.1406	3.5719	1 9/64	1.1406	28.9719	2 9/64	2.1406	54.3719
5/32	0.1563	3.9688	1 5/32	1.1563	29.3688	2 5/32	2.1563	54.7688
11/64	0.1719	4.3656	1 11/64	1.1719	29.7656	2 11/64	2.1719	55.1656
3/16	0.1875	4.7625	1 3/16	1.1875	30.1625	2 3/16	2.1875	55.5625
13/64	0.2031	5.1594	1 13/64	1.2031	30.5594	2 13/64	2.2031	55.9594
7/32	0.2188	5.5563	1 7/32	1.2188	30.9563	2 7/32	2.2188	56.3563
15/64	0.2344	5.9531	1 15/64	1.2344	31.3531	2 15/64	2.2344	56.7531
1/4	0.2500	6.3500	1 1/4	1.2500	31.7500	2 1/4	2.2500	57.1500
17/64	0.2656	6.7469	1 17/64	1.2656	32.1469	2 17/64	2.2656	57.5469
9/32	0.2813	7.1438	1 9/32	1.2813	32.5438	2 9/32	2.2813	57.9438
19/64	0.2969	7.5406	1 19/64	1.2969	32.9406	2 19/64	2.2969	58.3406
5/16	0.3125	7.9375	1 5/16	1.3125	33.3375	2 5/16	2.3125	58.7375
21/64	0.3281	8.3344	1 21/64	1.3281	33.7344	2 21/64	2.3281	59.1344
11/32	0.3438	8.7313	1 11/32	1.3438	34.1313	2 11/32	2.3438	59.5313
23/64	0.3594	9.1281	1 23/64	1.3594	34.5281	2 23/64	2.3594	59.9281
3/8	0.3750	9.5250	1 3/8	1.3750	34.9250	2 3/8	2.3750	60.3250
25/64	0.3906	9.9219	1 25/64	1.3906	35.3219	2 25/64	2.3906	60.7219
13/32	0.4063	10.3188	1 13/32	1.4063	35.7188	2 13/32	2.4063	61.1188
27/64	0.4219	10.7156	1 27/64	1.4219	36.1156	2 27/64	2.4219	61.5156
7/16	0.4375	11.1125	1 7/16	1.4375	36.5125	2 7/16	2.4375	61.9125
29/64	0.4531	11.5094	1 29/64	1.4531	36.9094	2 29/64	2.4531	62.3094
15/32	0.4688	11.9063	1 15/32	1.4688	37.3063	2 15/32	2.4688	62.7063
31/64	0.4844	12.3031	1 31/64	1.4844	37.7031	2 31/64	2.4844	63.1031
1/2	0.5000	12.7000	1 1/2	1.5000	38.1000	2 1/2	2.5000	63.5000
33/64	0.5156	13.0969	1 33/64	1.5156	38.4969	2 33/64	2.5156	63.8969
17/32	0.5313	13.4938	1 17/32	1.5313	38.8938	2 17/32	2.5313	64.2938
35/64	0.5469	13.8906	1 35/64	1.5469	39.2906	2 35/64	2.5469	64.6906

9/16	0.5625	14.2875	1 9/16	1.5625	39.6875	2 9/16	2.5625	65.0875
37/64	0.5781	14.6844	1 37/64	1.5781	40.0844	2 37/64	2.5781	65.4844
19/32	0.5938	15.0813	1 19/32	1.5938	40.4813	2 19/32	2.5938	65.8813
39/64	0.6094	15.4781	1 39/64	1.6094	40.8781	2 39/64	2.6094	66.2781
5/8	0.6250	15.8750	1 5/8	1.6250	41.2750	2 5/8	2.6250	66.6750
41/64	0.6406	16.2719	1 41/64	1.6406	41.6719	2 41/64	2.6406	67.0719
21/32	0.6563	16.6688	1 21/32	1.6563	42.0688	2 21/32	2.6563	67.4688
43/64	0.6719	17.0656	1 43/64	1.6719	42.4656	2 43/64	2.6719	67.8656
11/16	0.6875	17.4625	1 11/16	1.6875	42.8625	2 11/16	2.6875	68.2625
45/64	0.7031	17.8594	1 45/64	1.7031	43.2594	2 45/64	2.7031	68.6594
23/32	0.7188	18.2563	1 23/32	1.7188	43.6563	2 23/32	2.7188	69.0563
47/64	0.7344	18.6531	1 47/64	1.7344	44.0531	2 47/64	2.7344	69.4531
3/4	0.7500	19.0500	1 3/4	1.7500	44.4500	2 3/4	2.7500	69.8500
49/64	0.7656	19.4469	1 49/64	1.7656	44.8469	2 49/64	2.7656	70.2469
25/32	0.7813	19.8438	1 25/32	1.7813	45.2438	2 25/32	2.7813	70.6438
51/64	0.7969	20.2406	1 51/64	1.7969	45.6406	2 51/64	2.7969	71.0406
13/16	0.8125	20.6375	1 13/16	1.8125	46.0375	2 13/16	2.8125	71.4375
53/64	0.8281	21.0344	1 53/64	1.8281	46.4344	2 53/64	2.8281	71.8344
27/32	0.8438	21.4313	1 27/32	1.8438	46.8313	2 27/32	2.8438	72.2313
55/64	0.8594	21.8281	1 55/64	1.8594	47.2281	2 55/64	2.8594	72.6281
7/8	0.8750	22.2250	1 7/8	1.8750	47.6250	2 7/8	2.8750	73.0250
57/64	0.8906	22.6219	1 57/64	1.8906	48.0219	2 57/64	2.8906	73.4219
29/32	0.9063	23.0188	1 29/32	1.9063	48.4188	2 29/32	2.9063	73.8188
59/64	0.9219	23.4156	1 59/64	1.9219	48.8156	2 59/64	2.9219	74.2156
15/16	0.9375	23.8125	1 15/16	1.9375	49.2125	2 15/16	2.9375	74.6125
61/64	0.9531	24.2094	1 61/64	1.9531	49.6094	2 61/64	2.9531	75.0094
31/32	0.9688	24.6063	1 31/32	1.9688	50.0063	2 31/32	2.9688	75.4063
63/64	0.9844	25.0031	1 63/64	1.9844	50.4031	2 63/64	2.9844	75.8031
1"	1.0000	25.4000	2"	2.0000	50.8000	3"	3.0000	76.2000

MORE USEFUL CONVERSIONS

To convert decimal fractions of an inch to fractions of an inch.

Take the decimal fraction of feet and divide by 0.08333 (1/12th) and this will give you inches and decimals of an inch.

For example – 6.37 feet. Take the 0.37 feet and divide by 0.0833 = 4.44 inches .

So for 6.37 ft. we can also say 6 ft. – 4.44 in.

Now take the 0.44 in. and round it down to 0.4 which is 4/10"

We can now say 6.37' approximatly equals 6' – 4 4/10"

For fractions of an inch other than tenth's, take the decimal remainder of inches and divide by:

0.125 for the number of eighth's

0.0625 for the number of sixteenth's

0.03125 for the number of thirty-second's

0.015625 for the number of sixty-fourth's, and so on.

For example – 4.382 inches. For eighth's, divide the remainder, 0.382 by 0.125 and the answer is 3.056 so the fraction is a bit over 3 eighth's, therefore the answer ends up as approx. 4 3/8"

